










8148









8148N


NR	ELEMENT	8148N
E1	<div>D8148_1N</div> 	1
E2	<div>D8148_2N</div> 	1
E3	<div>D8148_3N</div> 	1
E4	<div>D8148_4N</div> 	1
E5		1
E6		1



8148N

Nr	Element	DIN	ELEMENT	$\Sigma$
1		-	S6x60	10
2		-	W6x60	9
21		DIN 125	8x16	1
77		-	K3_d30_A89 _G	1
213		-	Z_NA_1	1
214		-	Z_NA_2	1



8148N



# 8148N



ENG: „Due to the irregular shapes of natural robinia wood trunks, all dimensions provided in the documentation may slightly vary from the actual dimensions of the product.”

PL: “Z uwagi na nieregularne kształty naturalnych pni drewna robinii, wszystkie wymiary podane w dokumentacji mogą nieznacznie odbiegać od rzeczywistych wymiarów produktu.”




1

8148N




2

8148N



INST\_81\_198



3

8148N

3

B25 0,4m

min. 48H

